


 **Ratio**




MECH


1 Components







Direct Mount



Hanger Mount






4 Cage Stop Operation

1

SHIFT TO
SMALLEST




2



BUMP


3




PUSH


4

5







2



Full sus with large chain growth



3




6 B Gap Adjustment





ratiotechnology.com/mech/b-gap



B GAP SPEC



1 SHIFT TO SECOND LARGEST



Loosen axle before adjusting B gap on DM Mech

